



code.ironbaltic.com/u/yQQZmqD9c

SPEED LIMITER REMOVED VCU

CFMOTO UFORCE 600 **EV** (2025+)
Models with BOSCH ME17 VCU's

Code 96.4300

Version 15102025



Distributor **IronBaltic, Estonia**

Keep this manual for future reference!

If you need any spare parts, please send this packaging data to your local dealer or to Iron Baltic
sales@ironbaltic.com

Iron Baltic Ltd | +372 653 3711 | sales@ironbaltic.com | www.ironbaltic.com

SPECIFICATION

Pos.	Description	Code	Amount
1	VCU for UFORCE 600 EV (2025+)	96.4300ML	1
2	Sticker (IronBaltic)	PM.13.05.007	1



**ONLY FOR OFF-ROAD
AND/OR RACING USE!**



The end user is responsible for using this VCU with removed speed limiter and taking care of any penalties set by local authorities. This is an electronic device, and no warranty or replacement is implied. All sales are final.



Installing this VCU might void your ATV warranty!



IMPORTANT – SOFTWARE UPDATES

BEFORE ANY VEHICLE SOFTWARE UPDATE, REMOVE THE SPEED LIMITER REMOVED VCU AND INSTALL THE ORIGINAL VCU.

AFTER THE UPDATE, IT IS SAFE TO REINSTALL OUR VCU

INSTRUCTIONS

1. Make sure the vehicle ignition is turned OFF!
2. Disconnect battery negative terminal.
3. Locate the VCU and remove necessary screws to access the VCU.
4. Carefully disconnect the old VCU. Be careful not to damage contacts between VCU and connector.
5. Carefully connect new VCU. Be careful not to damage contacts between VCU and connector.
6. Reconnect the battery negative terminal.
7. Switch on the ignition and wait 60 seconds for the new VCU to communicate with the vehicle.
8. In some rare cases, fault code or engine light can occur. Usually, it is cleared after couple of engine starts and stops OR the fault code can be cleared with OBD diagnostic cable.
9. Have fun with your new VCU!



IRON BALTIC OÜ
Joa tee 17
Vääna 76903
Estonia / Europe

+372 6 533 711
sales@ironbaltic.com

www.ironbaltic.com
www.facebook.com/ironbaltic
www.youtube.com/user/ironbalticld